



Milling Department

Make	Model	Type	RPM	Pallet Pool	Tools	X	Y	Z	Spindle taper	Accessories
DMG/ MORI	NMV5000	5 Axis VMC	20,000	8	300	28,7	20,1	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	DMU 95 mono BLOCK	5 Axis VMC	20,000	NA	60	37,4	33,5	25,6	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	NH6300 DCGII	4 Axis HMC	10,000	12	330	41,3	35,4	38,6	50	Renishaw probe, 1000 psi coolant
DMG/ MORI	NH6300 DCGII	4 Axis HMC	10,000	12	330	41,3	35,4	38,6	50	Renishaw probe, 1000 psi coolant
DMG/ MORI	NH6300 DCGII	4 Axis HMC	10,000	12	330	41,3	35,4	38,6	50	Renishaw probe, 1000 psi coolant
DMG/ MORI	NH6300 DCG	4 Axis HMC	10,000	12	180	35,5	31,5	38,5	50	Renishaw probe, 1000 psi coolant
DMG/ MORI	NH4000 DCG	4 Axis HMC	20,000	11	300	22,0	22,0	24,8	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	NH4000 DCG	4 Axis HMC	20,000	11	300	22,0	22,0	24,8	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	NHX 5500	4 Axis HMC	12,000	2	120	31,5	31,5	34,6	50	Renishaw probe, 1000 psi coolant
DMG/ MORI	NHX 5500	4 Axis HMC	12,000	2	120	31,5	31,5	34,6	50	Renishaw probe, 1000 psi coolant
DMG/ MORI	Dura-Vertical 5100	4 Axis VMC	10,000	NA	30	41,3	20,9	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	Dura-Vertical 5100	4 Axis VMC	10,000	NA	30	41,3	20,9	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	Dura-Vertical 5100	4 Axis VMC	10,000	NA	30	41,3	20,9	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	CMX 1100 V	3 axis VMC	12,000	NA	30	43,3	22,0	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	CMX 1100 V	3 axis VMC	12,000	NA	30	43,3	22,0	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	CMX 1100 V	3 axis VMC	12,000	NA	30	43,3	22,0	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	CMX 1100 V	3 axis VMC	12,000	NA	30	43,3	22,0	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	CMX 1100 V	3 axis VMC	12,000	NA	30	43,3	22,0	20,1	40	Renishaw probe, 1000 psi coolant
DMG/ MORI	CMX 1100 V	3 axis VMC	12,000	NA	30	43,3	22,0	20,1	40	Renishaw probe, 1000 psi coolant
Haas	VF-3SSYT Super Speed	3 Axis VMC	12,000	NA	40+1	40,0	20,0	25,0	40	Renishaw probe, 1000 psi coolant
Haas	VF-2SSYT Super Speed	3 Axis VMC	12,000	NA	24+1	40,0	20,0	25,0	40	Renishaw probe, 1000 psi coolant
Haas	VF-2 SS Super Speed	3 Axis VMC	10,000	NA	30+1	30,0	16,0	20,0	40	Renishaw probe, 1000 psi coolant
Haas	VF-2 SS Super Speed	3 Axis VMC	10,000	NA	30+1	30,0	16,0	20,0	40	Renishaw probe, 1000 psi coolant
Haas	VF-2 SS Super Speed	5 Axis VMC	10,000	NA	30+1	30,0	16,0	20,0	40	Renishaw probe, 1000 psi coolant
Haas	VF-2 SS Super Speed	5 Axis VMC	10,000	NA	30+1	30,0	16,0	20,0	40	Renishaw probe, 1000 psi coolant
Haas	VF-2 SS Super Speed	5 Axis VMC	10,000	NA	30+1	30,0	16,0	20,0	40	Renishaw probe, 1000 psi coolant
Trak	MX-3	3 Axis	3,500	NA	1	32,0	16,0	16,0	R8	NA
Trak	MX-3	3 Axis	3,500	NA	1	32,0	16,0	16,0	R8	NA
Trak	DPM RX2	3 Axis	3,500	NA	1	32,0	16,0	16,0	40	NA
Trak	DPM RX2	3 Axis	3,500	NA	1	32,0	16,0	16,0	40	NA
Trak	DPM RX3	3 Axis	3,500	NA	1	32,0	17,0	16,0	40	NA
Trak	DPM RX3	3 Axis	3,500	NA	1	32,0	17,0	16,0	40	NA

Lathe Department

Make	Model	Axis	RPM	Max Dia	Spindle ID	Max OAL	Tool Stations
DMG/ MORI	NLX2500	2	4,000	14	2,9"	53"	10
DMG/ MORI	NL2500	2	4,000	14	2,9"	53"	12
DMG/ MORI	NL2500	2	4,000	14	2,9"	53"	12
DMG/ MORI	NL2500	2	4,000	14	2,9"	53"	12
DMG/ MORI	NL2500	2	4,000	14	2,9"	53"	12
DMG/ MORI	NLX2500	2	4,000	14	2,9"	53"	10
DMG/ MORI	NLX2500	2	4,000	14	2,9"	53"	10
Haas	TL-2	2	2,000	16	2,9"	48"	Manual
Haas	TL-2	2	2,000	16	2,9"	48"	Manual
Okuma	Crown Big Bore	2	3,500	10,63	2,75"	17"	12
Okuma	Crown Big Bore	2	3,500	10,63	2,75"	17"	12
Okuma	Crown Big Bore	2	3,500	10,63	2,75"	17"	12
Okuma	Cadet	2	3,500	10,63	2,5"	16"	12
Okuma	Cadet	2	3,500	10,63	2,5"	16"	12
Okuma	Cadet	2	3,500	10,63	2,5"	16"	12
Okuma	Cadet	2	3,500	10,63	2,5"	16"	12

Quality Department

Make	Model	X	Y	Z	Accessories
Mitutoyo	Brightstrato 710 CMM	27,8	39,6	23,8	Full DCC capacity
Brown & Sharpe	Global Performance CMM	35,4	47,2	31,5	Full DCC capacity, Off-line Progr'g
Hexagon	Global S CMM	35,4	47,2	31,5	Full DCC capacity, Off-line Progr'g
Keyence	IM-6225	3,9	7,9	NA	